

WHITE LIST

Approved self-locking panic locks for SmartHandle with DoorMonitoring

May only be used in single-leaf doors

The following optional lock functions cannot be used with the SimonsVoss bolt sensor:

- Split follower (outer thumb turn engaged to open electrically)
- Door strike function
- Electric locking function
- Motorised lock function
- Multiple-point locking system

Manufacturer	Designation	Centres distance	Door type	button position	Remarks	Release date
Abloy	EL060	92mm	Metal frame door	1		21.03.16
ABUS	TKZ40	72 mm	Solid leaf door	6	Use not recommended (lock fatigue strength)	06.10.14
BKS	2126 E	72 mm	Solid leaf door	1		06.10.14
Dorma	SVP 5719 / 5739	92 mm	Metal frame door	1		06.10.14
	SVP 52XX	72 mm	Solid leaf door	1		06.10.14
GEZE	IQ Lock M	92 mm	Metal frame door	4		06.10.14
	IQ Lock M	72 mm	Solid leaf door	2		06.10.14
Marc	825 (Auto/Panic)	70mm	Solid leaf door	5		18.03.16
SSF	Series 20/21 APK	72 mm	Solid leaf door	6		06.10.14
Wilka	1681	92 mm	Metal frame door	1		06.10.14
	5495	72 mm	Solid leaf door	1		06.10.14
WSS		92 mm	Metal frame door	1	Use not recommended (complex adjustment to doors in permanent mode)	06.10.14

BLACK LIST

Self-locking locks which **CANNOT** be used with the SmartHandle bolt sensor with DoorMonitoring

The following self-locking locks are not suitable for bolt sensor use:

Manufacturer	Designation	Centres distance	Door type	Remarks
Abloy	EL 165	70mm	Solid leaf door	No bolt button function
Eco Schulte	GBS 90	72 mm	Solid leaf door	Thumb-turn angle too wide
effeff	309X501PZ-----4	72 mm	Solid leaf door	Tampering protection prevents bolt button from functioning
	309X102PZ	92mm	Metal frame door	Thumb-turn angle too wide
Gege	Series 128	72 mm	Solid leaf door	No bolt button function